



INFORMATIONAL BULLETIN

Bulletin No. 204

Page 1 of 1

Effective: 7-17-90

Approved: *[Signature]*

CAUTION

The following signage shall be required to be permanently placed in the concrete slab inside either the garage door area or in the concrete slab adjacent to the building entry.

POST TENSION SLAB IN THIS BUILDING

Drilling or cutting into the encased cable tendons installed within the concrete slab without sufficient design could damage the structural integrity of the building.

Do not remove or damage any floor element before consulting a qualified engineer or your Building Department.